

GRAFICI TARATURE - SETTING RANGE DIAGRAMS



pressostato con contatto SPDT
pressure switch with SPDT contact

	PS3	PS3D	PS5	PS5D	PS12	PS12D	PS16D
Taratura di fabbrica ● <i>Factory setting</i>	1÷1,3 bar	1÷2 bar	2,4÷3 bar	2,4÷3,5 bar	5÷6,2 bar	5÷7 bar	5÷8 bar
Pressione max ammissibile <i>Max allowable pressure</i>	5 bar		12 bar			16 bar	

